



Tech Info Library

Macintosh SE: Video Problems

Article Created: 31 July 1987

Article Last Reviewed: 17 July 1992

Article Last Updated: 17 July 1992

BEFORE YOU START: Familiarize yourself with the Macintosh SE Technical Procedures. Be sure to follow proper ESD procedures.

PROBLEM DESCRIPTION: The Macintosh SE video screen slowly fades until there is no visible display at all.

PROBLEM CURE: Replace the Video Board, part number 661-0372 (or update to new part number). The video board is located on the back of the CRT assembly.

The video Board provides video amplification and over-voltage protection to the video circuit.

Copyright 1987, 1988, 1992 Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2268