



Tech Info Library

Hard Disk 20 P/C: First Time Start-Up = Init Failed

This article last reviewed: 29 April 1988

PROBLEM DESCRIPTION: When initializing a Hard Disk 20 with a known good Mac, the Mac displays an "Init Failed" message.

CAUSE: The HD 20 may have a failed Controller PCB.

CURE: Replace the modules in this order:

1. Controller PCB
2. Analog PCB/HDA Module

If this cure does not resolve the problem, go to the Technical Procedures to obtain a General Troubleshooting procedure.

Copyright 1988 Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1604