



Tech Info Library

Macintosh System 6.0 Installation Recommendations

This article last reviewed: 16 June 1988

When updating Macintosh system software to version 6.0, be sure to start up from the System Tools disk. Do not just switch-launch to it. Without a clean restart, programs and INITs can interfere with proper installation.

After performing what seemed to be proper installations on a variety of Macintoshes, engineers were getting consistent (though sometimes intermittent) error messages when restarting the systems. The errors included:

- "Unable to load needed resources" on startup.
- ID errors 02, 07, 10, 11, etc. when running applications or performing simple events.
- RAM Cache could be changed only to 1596.

These errors varied, depending on the type of Macintosh on which the installation was performed and the types of CDevs and INITs contained in the System files when upgraded. For example, it mattered if either Menu Clock or Vaccine (even though turned off) were present.

The above errors disappeared after deleting the recently updated System Folder, restarting the Macintosh with the System Tools disk, and reinstalling the software. Therefore, always start up from the Installer disk when installing or upgrading software to ensure a complete installation takes place.

Copyright 1988 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3051