Quadra 650, IIvx & IIvi: Replacing Top Case Screw (6/94)

Article Created: 22 March 1993		
Article Reviewed/Updated: 23 June 1994		
* RESTRICTED: Apple Internal and Support Providers	Only	*
Not For General Public Release		

Can the top case screw in the Macintosh IIvx, Macintosh IIvi, Performa 600, Quadra/Centris 650, or Power Macintosh 7100 be replaced?

DISCUSSION -----

TOPIC -----

The top case screw used in these products is a captive screw, it is not designed to be replaced if it should be damaged or broken. Drilling out the hole to install a different screw is not recommended as further damage to the case or top cover is possible.

There have been a few reports that this screw has broken. Should this occur, the whole bottom case would need to be replaced.

This screw is not required to operate the computer, so if it breaks or is damaged, the user has a choice to either ignore it or have a new bottom case installed.

Article Change History: 23 Jun 1994 - Clarified wording. Copyright 1993-94, Apple Computer, Inc.

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11827