



Tech Info Library

ImageWriter II: Bent Carrier Shaft Problem

Article Created: 18 April 1991

Article Last Reviewed:

Article Last Updated:

TOPIC -----

The carrier-shaft bushing on the left and right of the printhead assembly were broken on our ImageWriter II; we replaced both items. Now, the left side is too snug when the right side is adjusted properly, and the right side has too much of a gap when the left side is adjusted properly.

DISCUSSION -----

Other than playing around with more shim kits, you probably are looking at a bent carrier shaft. If the shaft is straight, then you should be able to adjust the printer with the shim kits; all but the very worst gap problems can be solved this way.

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7644