

LaserWriter Pro 810: Common RCF Errors (7/96)

Article Created: 11 July 1996

TOPIC -----

This article describes the most common errors that can appear on the Remote Control Facility (RCF) when the LaserWriter Pro 810 printer is powered on.

DISCUSSION -----

The following error appears when the LaserWriter Pro 810 printer has a thinnet Ethernet connector, and is not connected to a properly terminated thinnet network:

LAN XLP FAIL Error Level = 03

Server -910- Ethernet cable possibly open at 0 ns (0 ft thin, 0 ft thick) Server -922- Non-fatal error detected by selftest, code = ++++2

This error does not affect other forms of networking or printing.

The following error appears when the LaserWriter Pro 810 printer has a twisted pair Ethernet connector, and is not connected to a properly terminated twisted pair network:

LAN XLP FAIL Error Level = 08 Server -922- Non-fatal error detected by selftest, code = +++++2

Copyright 1996, Apple Computer, Inc.

Keywords: <None>

This information is from the Apple Technical Information Library.

19960715 07:36:30.00

Tech Info Library Article Number: 20160