LaserWriter: Blank Test Page May Be From Downloaded PostScript

Article Created: 12 April 1991
Article Last Reviewed:
Article Last Updated:

TOPIC ---

My LaserWriter IINTX works normally, except that the test print page is
blank. The unit prints all other pages with no problem. What does this
mean?

DISCUSSION --

If you have downloaded any PostScript programs to the printer, the test
page may have been blanked out unintentionally. If this is the case, the
fact that the sheet is blank does not point to any hardware failure.

If you have not downloaded any PostScript programs the blank test page
could be a sign of future I/O problems.
Copyright 1991 Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7528