



# Tech Info Library

## Macintosh SE and Radius Full Page Display

Article Created: 5 December 1988  
Article Last Reviewed: 17 July 1992  
Article Last Updated:

### Problem:

A Macintosh SE with a Radius FPD Monitor and Radius FPD Board installed with display problems. The Macintosh SE screen has thick vertical black and white lines on boot up. The Radius FPD Monitor has small vertical dashed lines on screen.

### Cure:

This caused by a faulty expansion slot on Macintosh SE Motherboard. The Macintosh SE Motherboard should be replaced.  
Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3458