# Tech Info Library

## Display Card 8-24 GC: Control Panel 7.0.1 Corrects Problems

Article	Created:	23	June	1	992	}		
Article	Reviewed	/Upc	dated:	:	30	September	1994	

Topic ------

The software control panel " $8 \cdot 24$  GC" that ships with the Macintosh Display Card  $8 \cdot 24$  GC enables graphics acceleration with the card.

Apple has identified a bug in version 7.0 of the "8.24 GC" control panel. Although graphics are accelerated, the overall system slows because the cache is disabled. Performance is not enhanced, and in some cases performance is degraded.

Discussion -----

### Which systems are affected?

\_\_\_\_\_

The problem affects Macintosh 68030-based systems -- specifically the Macintosh IIcx, IIci, IIsi, and IIfx -- with Macintosh Display Cards  $8 \cdot 24$  GC installed.

IMPORTANT NOTE: In 68040-based systems, the Macintosh Display Card  $8 \cdot 24$  GC disables acceleration. Apple continues to recommend that Quadra owners use the on-board video. The  $8 \cdot 24$  GC control panel is not designed for use with 68040-based systems.

#### What is the fix?

\_\_\_\_\_

The fix is a new control panel: "8•24 GC" version 7.0.1. The new control panel fully supports System 7 (with or without 7.0 Tune-Up), and corrects the data cache problem in 68030-based Macintosh systems.

#### System requirements

\_\_\_\_\_\_

To use version 7.0.1 of the "8.24 GC" control panel, you need:

- System 7.0 or greater (do not use System 6.0.x).
- At least 3MB RAM.

#### Installation

-----

Here's how to install "8.24 GC" 7.0.1 in a 68030-based Macintosh.

- 1) Drag the " $8 \cdot 24$  GC" icon into the System folder on your startup disk. System 7 will place it in the Control Panels folder for you.
- 2) Restart your Macintosh. A picture of a rocket will move up your screen, indicating that the software has been installed correctly and acceleration is enabled.

If the rocket does not move up your screen, appearing instead with a red line through it, there has been a problem installing the software. Check your Display Card  $8 \cdot 24$  GC manual for troubleshooting information.

These articles can help you locate software updates mentioned here:

- Where To Find Apple Software Updates
  Lists online services for "free" Apple software updates
- Obtaining Apple Product Support in the USA Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library

Article Change History:

30 Sep 1994 - Removed binary attachment. Explained where to located software.

02 Feb 1993 - Updated to explain how to locate the binary attachment if you are not using the on-line version of AppleLink.

Copyright 1992-1994, Apple Computer, Inc.

Keywords: <None>

-----

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10405