

## Apple Personal Modem: Correction to User's Manual

This article last reviewed: 30 March 1988

In the Apple Personal Modem User's Manual (P/N 030-2001-C), page 84, Figure F-1, the picture and pin numbering of the 8-pin connector are incorrect. The APM port should be numbered from right to left, starting with the two-pin row at the bottom. The APM connector should (generally) look like this:

"Female" mini din-8 8 7 6 connector 5 4 3 2 1

Here's the diagram for the cable plugs:

"Male" mini din-8 6 7 8 connector 3 4 5

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

\_\_\_\_\_\_

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2807