

Tech Info Library

Refurbishment & Life Cycle: For LW Models (1/94)

Article Created: 22 November 1993

Article Revised/Updated: 11 January 1994

TOPIC -----

Are there refurbishment kits for Apple Laser printers? If not, is there a List of parts that are "recommended for replacement"?

Also, what is the expected life of these printers?

DISCUSSION -----

The LaserWriter II engine is the only Apple printer that has a refurbishment kit.

LaserWriter II

- Refurbishment kit part number: 652-0597
- Minimum life expectancy is 300K pages.

Personal LaserWriter SC/NT/NTR/LS

- Has a life of 150K pages
- Recommended that the fuser be changed after 100K pages.

Select 300/310:

- Has a life of 150K pages or five years.
- Recommended that the fuser be changed after 100K pages.

Select 360:

- Has a life of 300K pages or five years.
- Recommended that the fuser be changed after 100K pages.

LaserWriter Pro 600/630:

- Has a life of 450K pages or five years.
- For that engine the following parts are recommended for replacement after 200K pages: Fuser Assembly

Transfer Roller

MP Tray Pickup Rollers MP Tray Guide Assembly Cassette Pickup Rollers

Personal LaserWriter 320:

• Print engine life: Up to 8K pages monthly maximum recommended

Article Change HIstory: 11 January 1994 - Added LW II and PLW families Copyright 1993-94, Apple Computer, Inc.

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 14015