

## Pascal: Interface cards in peripheral slot #3

The Pascal system will not appear to boot correctly on the standard Apple video if slot #3 has a Communications card, Serial card, or DC Hayes Micromodem card in it. Pascal reserves slot #3 for an external terminal, so when Pascal recognizes a card in this slot, it attempts to communicate with the assumed terminal and not with the default CONSOLE and SYSTERM (video and keyboard). Other cards may also cause this effect, which can be easily remedied by removing the card from slot #3. Apple Tech Notes

Keywords: <None>

\_\_\_\_\_

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 660