

Tech Info Library

PATHWORKS 1.0: No Official Support for HP LaserJet

| Article | Created: | 13 | August | 1991 |
|---------|----------|----|--------|------|
|---------|----------|----|--------|------|

Article Last Reviewed: Article Last Updated:

TOPIC -----

Does PATHWORKS 1.0 support HP LaserJet? Does the print driver from the PATHWORKS (either 6.0 or 7.0) support LaserJet?

DISCUSSION -----

Officially, PATHWORKS 1.0 Print Services only support following PostScript printers:

Printer Connected to the VAX computer through

Digital LPS20 Ethernet
Digital LPS40 Ethernet
Digital LPS40 Plus Ethernet

Digital LN03R Serial Connection

Apple printers: LocalTalk/Ethernet bridge or an RS-232 serial

connection

LaserWriter Plus LaserWriter IINT LaserWriter IINTX

The PATHWORKS print drivers are for the above PostScript printers only.

If you need more specific information or you have enhancement requests, contact Digital Technical Support directly.

For more information, search under: "Digital" Copyright 1991 Apple Computer, Inc.

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8608