



Tech Info Library

MacIrma 1.20: Use With MultiFinder

This article last reviewed: 20 September 1989

TOPIC-----

I have a Macintosh II with 5MB of memory under MultiFinder, running System 6.0.2. I use a DCA MacIrma board for IBM host connectivity. When I print five to ten mainframe screens in a row, the system freezes and must be restarted. Background printing is on, and there is no AppleShare Print Server on the network. Do you have any ideas?

DISCUSSION-----

According to our local MacIrma expert, this is a known problem in earlier versions of the software. Make sure that you are using version 1.20 of MacIrma, and the problem should disappear. If the problem does not clear up, contact DCA, Inc. For more details, search the Tech Info Library under "DCA." Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4589