

Power Macintosh 8100/110: No Official AV Card Support (7/95)

Article Created: 15 February 1995 Article Reviewed/Updated: 11 July 1995
TOPIC
I notice that the Power Macintosh $8100/110$ does not ship with an AV video card. Will the Power Macintosh AV video card work in a Power Macintosh $8100/110$?
DISCUSSION
While designed to function in any Processor Direct Slot (PDS) equipped Power Macintosh computer, the Power Macintosh AV Card was never thoroughly tested in the Power Macintosh $8100/110$. Therefore, Apple does not support the use of the AV card in the Power Macintosh $8100/110$.
Due to the similarity of the design of the Power Macintosh $8100/80$, $8100/100$, and $8100/110$, it is unlikely you will experience a problem when installing the AV card into a Power Macintosh $8100/110$.
However, because this configuration was not thoroughly tested by Apple, we cannot officially support this configuration if a problem arises.
Article Change History: 11 Jul 1995 - Reviewed for technical accuracy. 17 Mar 1995 - Revised compatibility statement of AV card in a Power Macintosh.
Support Information Services Copyright 1995, Apple Computer, Inc.
Keywords: kppc,kcompat
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17197