

QuarkXPress: System Hang When Faxing Through GeoPort (2/95)

Article Created: 09 December 1994 Article Reviewed/Updated: 16 February 1995

TOPIC -----

I am experiencing a system lock on my Power Macintosh 7100 AV when I try to fax a document from QuarkXPress 3.3.1 using my GeoPort. The document will image and it is then placed in the "Waiting to be faxed" folder. The Macintosh locks up and must be restarted with System 7.5 extensions only.

After I restart, I must reinstall the GeoPort software and restart again. Once the Macintosh restarts, the fax is sent immediately. This same procedure happens everytime I fax anything from Quark.

DISCUSSION -----

I recommend upgrading to the latest Express Fax/GeoPort software. In this case you should first install GeoPort for Power Macintosh 1.0.2, then install Express Modem 1.5.5. This combination will provide the latest and greatest versions of the software.

There was a known bug that caused the system to crash when there were faxes waiting to be sent at startup time.

Both GeoPort for Power Macintosh 1.0.2 and Express Modem 1.5.5 are available on AppleLink or Apple's WWW site on the internet (http://www.support.apple.com/).

These articles can help you locate software updates mentioned here:

- Where To Find Apple Software Updates Lists online services for "free" Apple software updates
- Obtaining Apple Product Support in the USA Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library

Article Change History: 16 Feb 1995 - Changed keyword and reviewed for technical accuracy.

Support Information Services Copyright 1994-95, Apple Computer, Inc. Keywords: sys75,kppc,knts

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16865