

## LaserWriter II: Using with Windows 2.11

This article last reviewed: 2 November 1989
TOPIC
This article discusses the correct version of Windows to use with a LaserWriter II
DISCUSSION
Microsoft Windows, used in conjunction with a LaserWriter II, sometimes has a problem of seeing ROM version I instead of PostScript 47, and thus refusing to print to it.
As of November, 1989, Microsoft UK has informed us that the latest versions of Windows (v2.11) and its PostScript driver (v3.1) do not suffer from this problem and will print to a LaserWriter II successfully. Copyright 1989 Apple Computer, Inc.
Keywords: <none></none>
This information is from the Apple Technical Information Library.
19960215 11:05:19.00
Tech Info Library Article Number: 4669